

An MND Statutory Board

Our ref : APPBCA-2023-04

01 Mar 2023

See Distribution List

Dear Sir/Madam

UPDATES TO THE APPROVED DOCUMENT (1 MARCH 2023)

This circular is to inform the industry on the update to the Approved Document with reference to BCA circular ref: APPBCA-2022-25 issued on 1 December 2022.

- There are no new requirements in this update. The update incorporates the standardised designs for replacement and reinstatement of safety barriers integrated with windows in existing residential buildings. The amendment to the Approved Document will take immediate effect.
- 3 Details of the changes to the Approved Document are shown in Annex A. The Standardised Designs will be set out in the updated Approved Document which can be downloaded from BCA's website from this link:

<u>https://www1.bca.gov.sg/docs/default-source/docs-corp-regulatory/building-control/approved-document-v7-04.pdf?sfvrsn=88213736_2</u>

- We would appreciate if you could share this circular with your members. If you need any further clarifications, please contact us through BCA's Online Feedback Form at https://www.bca.gov.sg/feedbackform/.
- 5 Thank you.

Yours faithfully

AR. ONG YU ZI JANE
DIRECTOR
BUILDING PLAN AND POLICIES DEPARTMENT
BUILDING PLAN AND MANAGEMENT GROUP
BUILDING AND CONSTRUCTION AUTHORITY
FOR COMMISSIONER OF BUILDING CONTROL



Annex A -AMENDMENTS TO THE APPROVED DOCUMENT 1 MARCH 2023

CURRENT VERSION 7.03	1 MARCH 2023 VERSION 7.04	COMMENTS
Section H SAFETY FROM FALLING		
H.3.1 The requirement in paragraphs H.2.1, H.2.1A and H.2.1B is deemed to be satisfied if a barrier is provided in accordance with the specifications set out in paragraphs H.3.2 to H.3.5.	H.3.1 The requirement in paragraphs H.2.1, H.2.1A and H.2.1B is deemed to be satisfied if a barrier is provided in accordance with the specifications set out in paragraphs H.3.2 to H.3.5. H.3.1A The requirements in paragraphs H.2.1, H.2.1A	Editorial Changes
	and H.2.1B are deemed to be satisfied for a safety barrier integrated with window at existing residential buildings, if such safety barrier is in accordance with the standardised design.	
	Note: For purposes of Regulation 2 of the Building Control Regulations 2003 and paragraph H3.1A, "standardised design" means the standardised design set out in Annex C in this Approved Document.	
	Annex C – Standardised Designs for replacement and reinstatement of safety barriers integrated with windows in existing residential buildings.	Rules relaxation. document (Annex C) added as acceptable solution.





An MND Statutory Board DISTRIBUTION (via e-mail):

President

Association of Consulting Engineers, Singapore (ACES) 18 Sin Ming Lane #06-01 Midview City Singapore 573960

President Institution of Engineers, Singapore (IES) 70 Bukit Tinggi Road

Singapore 289758

President

Real Estate Developers' Association of Singapore (REDAS) 190 Clemenceau Avenue #07-01 Singapore Shopping Centre Singapore 239924

President

Singapore Contractors Association Limited (SCAL) Construction House 1 Bukit Merah Lane 2 Singapore 159760

President

Singapore Institute of Architects (SIA) 79 Neil Road Singapore 088904

President

Singapore Institute of Building Limited (SIBL) 9, Ah Hood Road, #02-04, Singapore 329975

President

Singapore Institute of Surveyors & Valuers (SISV) 110 Middle Road #09-00 Chiat Hong Building Singapore 188968

President

Society of Project Management (SPM) 168 Jalan Bukit Merah Connection One #10-01 Singapore 150168 c/o SIPM Consultants Pte Ltd

President

Board of Architects (BOA) 5 Maxwell Road 1st storey Tower Block MND Complex Singapore 069110



President

Professional Engineers Board, Singapore (PEB) 52 Jurong Gateway Road #07-03 Singapore 608550

President

Singapore Lift & Escalator Contractors & Manufacturers Association (SLECMA) 3 Raffles Place #06-01 Bharat Building Singapore 048617

President

Singapore Hotel Association 17 Cantonment Road Singapore 089740

Chairman

The Association of Shopping Centres (Singapore) 91 Tanglin Road #03-01 Tanglin Place Singapore 247918

President

Singapore Structural Steel Society (SSSS) 1 Liang Seah Street #02-11/12 Liang Seah Place Singapore 189022

Director of Infrastructure School Campus Department Ministry of Education 1 North Buona Vista Drive Singapore 138675

Deputy Director
Project Development & Management 3
Building Quality Group
Housing & Development Board
HDB Hub
480 Lorong 6 Toa Payoh
Singapore 310480

Deputy Chief Executive Infrastructure & Development Land Transport Authority (LTA) 1 Hamphire Road Block 8 Level Singapore 219428

Director Technical Services Division JTC Corporation (JTC) 8 Jurong Town Hall Road The JTC Summit Singapore 609434

Senior Director (Building & Estates Management)
People's Association (PA)

52 Jurong Gateway Road #11- 01 Singapore 608550 Tel: 1800 3425 222 | Fax: (65) 6334 4287

www.bca.gov.sg

9 King George's Avenue Singapore 208581

Director
Special Projects & Procurement Department
PUB, Singapore National Agency
40 Scotts Road #08-01
Environment Building
Singapore 228231

Chief(Sports Facilities) Sport Singapore 3 Stadium Drive Singapore 397630

Chief Executive Officer Urban Redevelopment Authority (URA) 45 Maxwell Road, The URA Centre Singapore 069118

Director
Building and Infrastructure
Defence Science & Technology Agency
1 Depot Road
Defence Technology Tower A
Singapore 109679

Head (Fire Safety and Building Control) Building and Infrastructure Defence Science & Technology Agency 71 Science Park Drive Singapore 118253

Manager (Architectural Plans)
Building and Infrastructure
Defence Science & Technology Agency
71 Science Park Drive
Singapore 118253

Deputy Chief Executive Officer Sentosa Development Corporation 33 Allenbrooke Road, Sentosa Singapore 099981

Chief
Health Infrastructure Project
MOH Holdings Pte Ltd
1 Maritime Square #11-25
HarbourFront Centre
Singapore 099253

Specialists Trade Alliance of Singapore (STAS) 24 Peck Seah Street, #07-11 Nehsons Building Singapore 079314

52 Jurong Gateway Road #11- 01 Singapore 608550 Tel: 1800 3425 222 | Fax: (65) 6334 4287

www.bca.gov.sg

Singapore International Facility Management Association (SIFMA) 200 Braddell Road, #01-03 Block H, BCA Braddell Campus Singapore 579700

Association of Property and Facility Managers (APFM) 110 Middle Road #09-00 Chiat Hong Building Singapore 188968

President Singapore Green Building Council (SGBC) 200 Braddell Road Block H, Level 2 BCA Braddell Campus Singapore 579700

All CORENET e-Info Subscribers